



After market products			
EP/GP#	POS.NR.	QTY.	CANYON#
	48	1x	I0006305
GP7045-01	13 (EPI195-01), 14 (EPI365-01), 15, 17 (EPI178-01)	1x 2x 2x 2x	I0007494
GP7057-01	1 (EPI368-01), 2	1x 2x	I0007857
GP7059-01	43 (EPI367-01), 44 (EPI313-01)	1x 1x	I0007899
GP7038-01	20, 21	2x 2x	I0007487
GP7039-01	15, 16	2x 2x	I0007488
GP7040-01	15, 38	2x 2x	I0007489
GP7041-01	15, 20	12x 4x	I0007490
GP7042-01	EP0675-01, EP0674-01, EPI118-01, Screw M6x50	1x 1x 1x 1x	I0007491
GP7043-01	18 (EPI185-01), 19 (EPI174-01), 22 (EPI177-01), 23 (EPI186-01), 30	1x 2x 2x 1x 1x 1x	I0007492
GP7046-01	12 (EPI194-01), 15, 32, 35 (EPI196-01),	2x 2x 2x 2x	I0007495
GP7050-01	9, 15, 37 (EPI179-01), 39 (EPI164-01), 40 (EPI187-01)	2x 4x 4x 2x 2x	I0007496
GP7051-01	7 (EPI176-01), 8 (EPI364-01), 9, 34 (EPI181-01), 35 (EPI182-01), 36 (EPI183-01)	1x 1x 1x 1x 1x 1x	I0007497

TORQUE CF | M106-01



REVISION 00 | 08.07.2021

THIS TECHNICAL DOCUMENT, INCLUDING ANY PICTURES AND VIDEOS PROVIDED, IS COPYRIGHT-PROTECTED AND INTENDED SOLELY FOR USE IN YOUR OPERATION BY DULY AUTHORIZED PERSONNEL